

i50/i55


MCU-UPDATE




With some ESX Smart Naviceivers of the i50 / i55 series there may be problems with learning the steering wheel remote control in connection with vehicles of the Fiat Ducato platform. This problem can be solved with a current MCU update.

To perform the update, please proceed as follows:


1. On a computer with an Internet connection, download the update file from www.esxnavi.de/mcu
2. Unzip "i50-i55-MCU-Update.zip" and copy the file to an empty storage medium (USB stick or SD card).
3. Then insert the storage medium into the corresponding slot on your Naviceiver.




4. After selecting the device, tap on "Settings" in the main menu.



5. Open the "Car settings".



6. Tap on MCU update.



7. Select the storage medium on which the MCU update is saved.

8. The MCU update will now start automatically. When the update is complete, the device will restart. Then disconnect the storage medium from the device.

ATTENTION: Never interrupt the power supply to the device during the entire process. Do not remove the storage medium prematurely either, otherwise the device could be damaged.

NOTE: We assume no liability for any damage, malfunctions or lost data on your device or computer that may result from the download or installation.